Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW0951/1
Work Order Type: Weatherization
Audit Name: Audit (65)

CLIENT INFORMATION

Client Name: Address:
Client ID: 12012NW0951

Alt. Client ID:

AGENCY INFORMATION

Agency: N.W.T.N.E.D.C Agency Phone: (731) 364-3228

Address: Fax:

dresden, TN Email Address:

Agency Contact: Smith, Randy Work Phone:

Cell Phone:

Email Address:

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

<u>COMMENT</u>

Measures

| / | Measure 1 Wind | dow Replacement | | | Compone | nts 2,1 | | | Inspected |
|------------|--|--|----------------------|----------------|-----------------------------------|---------|----------|------------------|-----------|
| C | omment | | | | | | | | |
| | | | | | Estimate | d | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Windows | Window Replacement | SqFt | 51.67 | | | | | |
| | | replace with vinyl approx size 31 x 60 | | | | | | | |
| 2 | Labor | Window Replacement | SqFt | 51.67 | | | | | |
| | | replace with vinyl approx 31 x 60 | | | | | | | |
| 3 | Other | Window Replacement | Each Window | 4 | | | | | |
| 0 | ther Detail | | | | | | - | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measure | Sub Total: | |] ; | Sub Total: | |
| | Field Notes: | | | | | | | | |
| | | | | | | | | | |
| // | Measure 2 DWI | H Tank Insulation | | | Componei | nts | | | Inspected |
| | Measure 2 DWF | H Tank Insulation | | | Compone | nts | | | Inspected |
| | | H Tank Insulation | | | Compone Estimate | | | Actual | Inspected |
| C | | H Tank Insulation Description / Comment | Units | Qty | - | | Qty | | Inspected |
| C : | omment | | <i>Units</i> Each | | Estimate | d | Qty | Actual | |
| # 1 | omment Material / Labor Hot Water | Description / Comment | | Qty | Estimate | d | Qty | Actual | |
| # 1 | omment Material / Labor Hot Water Equipment | Description / Comment DHW Tank Insulation | Each | Qty 1 | Estimate | d | Qty | Actual | |
| # 1 | Material / Labor Hot Water Equipment Labor | Description / Comment DHW Tank Insulation | Each | Qty 1 | Estimate | d | Qty | Actual | |
| # 1 | Material / Labor Hot Water Equipment Labor | Description / Comment DHW Tank Insulation | Each | Qty 1 | Estimate | d | Qty | Actual | |
| # 1 | Material / Labor Hot Water Equipment Labor | Description / Comment DHW Tank Insulation | Each | Qty 1 1 | Estimate | d | | Actual | |
| # 1 2 O | Material / Labor Hot Water Equipment Labor | Description / Comment DHW Tank Insulation | Each | Qty 1 1 | Estimate Unit Cost | d | | Actual Unit Cost | |
| # 1 2 O | Material / Labor Hot Water Equipment Labor ther Detail | Description / Comment DHW Tank Insulation | Each | Qty 1 1 | Estimate Unit Cost | d | | Actual Unit Cost | |
| # 1 2 O | Material / Labor Hot Water Equipment Labor ther Detail | Description / Comment DHW Tank Insulation | Each | Qty 1 1 | Estimate Unit Cost | d | | Actual Unit Cost | |

| Measure 3 DW Comment | H Pipe Insulation | | | Componen | ts | | | Inspected |
|-------------------------|---|-------|---------|--------------|----------|------|------------|-----------|
| | | | _ | Estimated | <u> </u> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | DHW Pipe Insulation | Each | 1 | | | | | |
| 2 Labor | DHW Pipe Insulation | Each | 1 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | |] [] | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| Measure 4 Wal | II Insulation | | | Componen | ts 1 | | | Inspected |
| Comment | | | | | | | | |
| | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Wall Insulation - Cellulose, Blown - 2x4 Filled | SqFt | 206.2 | | | | | |
| 2 Labor | Wall Insulation - Cellulose, Blown - 2x4 Filled | SqFt | 206.2 | | | | | |
| Other Detail | | | , | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | | | | | | |

| Measure 5 Wa | II Insulation | | | Componen | ts 3 | | | Inspected |
|--------------------|---|-------|---------|--------------|-------------|-----|------------|-----------|
| Comment | | | | | | | | |
| | | | | Estimated | <u> </u> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Wall Insulation - Cellulose, Blown - 2x4 Filled | SqFt | 252 | | | | | |
| 2 Labor | Wall Insulation - Cellulose, Blown - 2x4 Filled | SqFt | 252 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| Measure 6 Wa | II Insulation | | | Componen | ts 2 | | | Inspected |
| | | | | Estimated | <u> </u> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Wall Insulation - Cellulose, Blown - 2x4 Filled | SqFt | 223.9 | | | | | |
| 2 Labor | VA / = 11 1 = = = 1 = 42 = = | SqFt | 223.9 | | | | | |
| | Wall Insulation - Cellulose, Blown - 2x4 Filled | oqi t | | | | | | |
| Other Detail | Cellulose, Blown - 2x4 | Oqi t | | | | | , | |
| Other Detail | Cellulose, Blown - 2x4 | Oqi t | | | | | | |
| Other Detail | Cellulose, Blown - 2x4 | | | | | | | |
| Other Detail | Cellulose, Blown - 2x4 | | | e Sub Total: | | | Sub Total: | |

| Comment | l Insulation | | | Componen | its 4 | | | Inspected |
|---|--|----------------------|-----------------|--------------|----------|-----|------------|--------------------|
| | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Wall Insulation - Cellulose, Blown - 2x4 Filled | SqFt | 198.3 | | | | | |
| 2 Labor | Wall Insulation - Cellulose, Blown - 2x4 Filled | SqFt | 198.3 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | |] ; | Sub Total: | |
| | | | | | | | | |
| Measure 8 Floo | or Ins. R-19 | | | Componen | | | | Inspected |
| Comment | | Units | | Estimated | <u> </u> | Otv | Actual | |
| Comment | Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 | <i>Units</i> SqFt | Qty 1220 | • | | Qty | | Inspected Total |
| Comment # Material / Labor | Description / Comment Floor Insulation - Fiberglass Faced Batt - | | Qty | Estimated | <u> </u> | Qty | Actual | |
| # Material / Labor 1 Insulation | Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt - | SqFt | Qty 1220 | Estimated | <u> </u> | Qty | Actual | |
| # Material / Labor 1 Insulation 2 Labor | Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt - | SqFt | Qty 1220 | Estimated | <u> </u> | Qty | Actual | |
| # Material / Labor 1 Insulation 2 Labor | Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt - | SqFt | Qty 1220 | Estimated | <u> </u> | Qty | Actual | |

| 1 Cooling Wir Equipment 2 Labor Wir Other Detail Field Notes: Measure 10 Window | ndow A/C - | Units Each | Qty 1 1 Measure | Estimated Unit Cost | Total | Qty | Actual Unit Cost | Total |
|---|---------------------|----------------|-----------------|---------------------|--------|--------------|------------------|---------|
| 1 Cooling Wir Equipment 2 Labor Wir Other Detail Field Notes: Measure 10 Window | ndow A/C - | Each | 1 1 | | Total | | | rotal |
| Equipment 2 Labor Wir Other Detail Field Notes: Measure 10 Window | | Each | 1 | e Sub Total: | | | Sub Total: | |
| Other Detail Field Notes: Measure 10 Window | ndow A/C - | | | Sub Total: | | | Sub Total: | |
| Field Notes: Measure 10 Window | | | Measure | Sub Total: | | | Sub Total: | |
| Measure 10 Window | | | Measure | Sub Total: | | | Sub Total: | |
| Measure 10 Window | | | Measure | e Sub Total: | |] . | Sub Total: | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| Measure 10 Window | | | | | | | | |
| Comment | Replacement | | | Componen | | | | nspecte |
| # Material / Labor Des | scription / Comment | Units | Qty | Estimated Unit Cost | Total | Qty | Actual Unit Cost | Total |
| | ndow Replacement | SqFt | 26.67 | Omit Cost | I Otal | Qiy | Omit Cost | TOTAL |
| | | | | | | 1 | | |
| 2 Labor Wir | ndow Replacement | SqFt | 26.67 | | | | | |
| 3 Other Wir | ndow Replacement | Each Window | 2 | | | | | |
| Other Detail | | | | | |] | | |
| | | | | | |] []] [] | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |

| | Measure 11 Stor Comment | m Windows | | | Componen | ts 5 | | ı | Inspected |
|---|--|----------------------------------|----------------------|--------------|---------------------|-------------|-----|------------|-----------------|
| | Jonne III | | | | Estimated | | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Windows | Storm Window | SqFt | 7 | | | | | |
| 2 | Labor | Storm Window | SqFt | 7 | | | | | |
| 3 | Other | Storm Window | Each Window | 1 | | | | | |
| (| Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] , | Sub Total: | |
| | Measure 12 CO I | | | | | | | | |
| | | Monitor is Needed | | | Componen | ts | | ı | Inspected |
| | | | | | Componen Estimated | | | Actual | Inspected |
| # | Material / Labor | Description / Comment | Units | Qty | • | | Qty | | Inspected Total |
| | | Description / Comment | <i>Units</i> Each | Qty 1 | Estimated | | Qty | Actual | |
| 1 | Material / Labor Health and Safety | Description / Comment | | | Estimated | | Qty | Actual | |
| 1 | Material / Labor Health and Safety Items | Description / Comment CO monitor | Each | 1 | Estimated | | Qty | Actual | |
| 1 | Material / Labor Health and Safety Items Labor | Description / Comment CO monitor | Each | 1 | Estimated | | Qty | Actual | |
| 1 | Material / Labor Health and Safety Items Labor | Description / Comment CO monitor | Each | 1 | Estimated | | Qty | Actual | |
| 1 | Material / Labor Health and Safety Items Labor | Description / Comment CO monitor | Each Hour | 1 | Estimated | | | Actual | |

| | Measure 13 Fix I | mproper Venting (Cloth | nes Dryer |) | Componer | nts | | | Inspected |
|---|-------------------------|---|-----------|--------|--------------|-------|----------|------------|-----------|
| C | omment | | | | | | | | |
| | | | | | Estimated | d | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Equipment | Each | 1 | | | | | |
| | | properly vent dryer to exterior of house with metal flex and new outside cover | | | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | |
| C | Other Detail | | | | | | | | |
| L | | | | | | | <u> </u> | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | , | Sub Total: | |
| | Measure 14 Smo | ke Detector is Needed | | | Componer | nts | | | Inspected |
| | | | | | Estimated | d | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Smoke detector | Each | 1 | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | | | | | |
| | | | | | | | | | |

| | Measure 15 gene | | | Componen | ts | Inspected | | | |
|---|--|---|--------|----------|--------------|-----------|--------|------------|-------|
| C | omment | | | | | | | | |
| | | | | | Estimated | 1 | Actual | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Construction Materials/Hardwar e | floor repair | Each | | | | | | |
| | | replace a 4 x 8 section of floor in kitchen | | | | | | | |
| C | Other Detail | | | 1 | 1 | | | 1 | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | - | | | | |
| L | | | Work O | rder Gra | and Total: | | Gran | d Total: | |